SERVICE TIPS

FAST AID HOT LINE: 800-323-0666
EXCEPT ILLINOIS: 312-981-1000 Ext. 215
TELEX: 253290

TAITO®

82-19

- [ ] MANDATORY
- [ ] ON FAILURE ONLY
- [x] FOR YOUR INFORMATION

ATTN: SERVICE MANAGERS

GAME: THE ELECTRIC YOYO

SUBJECT: UNABLE TO GIVE MORE THAN THREE YOYO'S A GAME.

SOLUTION: UPGRADE ROM REVISION

PARTS NEEDED: ONE YOYO ROM SET REV. (YO) PART NUMBER 16-00015-000

DISPOSITION OF OLD PARTS: RETURN FOR CREDIT.

PROCEDURE: IF THE ROMS ON THE ROM I/O BOARD ARE (YU) ROMS, REPLACE THEM WITH (YO) REV. ROMS.

TAITO AMERICA CORPORATION
1256 Estes Ave., Elk Grove Village, IL 60007